

"BURNSIDE"

(Received at London Office..... 14 OCT 1939)

No. 6489 Port

Glasgow

Date 12th October, 1939.

We request that the Refrigerating Machinery and Appliances of the ~~Steam Ship~~ <sup>Motor</sup>

building by Barclay, Curle & Co. Ltd., for Burns, Philp & Co. Ltd.,

Builders' Yard No. 676 may be specially surveyed during construction with a view to the notation

\*RMC (in red) (i.e. Refrigerating Machinery Certificate) being made in the Register Book.

The vessel is intended for Classification in Lloyd's Register.

We hereby engage to pay the established fees, as follows, viz.:—

In the case of vessels classed in Lloyd's Register Book

	£	s.	d.
Under 40,000	-	-	6 0 0
40,000 and under 80,000	-	-	9 0 0
80,000 and under 120,000	-	-	12 0 0
120,000 and under 180,000 in not more than 6 compartments	-	-	15 0 0
120,000 and under 180,000 in more than 6 compartments	-	-	18 0 0
180,000 and under 250,000 in not more than 8 compartments	-	-	21 0 0
180,000 and under 250,000 in more than 8 compartments	-	-	24 0 0
250,000 and under 330,000 in not more than 10 compartments	-	-	24 0 0
250,000 and under 330,000 in more than 10 compartments	-	-	27 0 0

	£	s.	d.
330,000 and under 400,000 in not more than 12 compartments	30	0	0
330,000 and under 400,000 in more than 12 compartments	36	0	0
400,000 and under 500,000 in not more than 14 compartments	36	0	0
400,000 and under 500,000 in more than 14 compartments	42	0	0
500,000 and under 600,000 in not more than 16 compartments	42	0	0
500,000 and under 600,000 in more than 16 compartments	48	0	0
600,000 and above in not more than 18 compartments	48	0	0
600,000 and above in more than 18 compartments	54	0	0

In the case of vessels not classed in Lloyd's Register Book the fees will be double the amounts shown above.

In exceptional cases an additional charge will be made according to the service performed, and in all cases where travelling expenses are incurred by the Surveyors in connection with the above services, they are to be defrayed by the parties interested.

In no case can a record of RMC be made in the Register Book until all fees, travelling expenses, &c., due to the Society are paid.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

Sigs. auth. for Surveyors of Refrigerating Machinery  
23/10/39

J. & E. Hall, Ltd.  
FOR BARCLAY, CURLE & CO., LTD.

To the Secretary,

Signature

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C. (3)

005239-005248-0145

Oil Storage Tanks, where adjacent to the insulated chambers, state what provision has been made for ventilating