

Date of writing Report 14th October 1921 When handed in at Local Office 14th October 1921 Port of Göthenburg  
No. in Survey held at Göthenburg Date, First Survey 10th October Last Survey 10th October 1921  
Reg. Book Supplement (No. of Visits 2)  
39944 on the ~~Wood, Iron or Steel~~ Sc. Ls. "WATERWAY" Master i

TONNAGE:—	Built at	Limhamm	By whom	Limhamns Skepssaw	When	1991	YEAR.	MONTH.
GROSS 750	Owners	Waterway Steamships Ltd.			Port belonging to	Cardiff		
UNDER DK.	Owners' Address	(if not already recorded in Appendix to Register Book).						
NET								

Surveyed Afloat or in Dry Dock? Afloat Name of Dock                      Destined Voyage                     

WB=Cell DBorDBa                      feet; uE&B                      feet; f                      feet; }  
total capacity                      tons. FPT                      tons; APT                      tons; MT                      feet                      tons. } Particulars of Classification (which must be inserted  
precisely as in Register Book & Supplements).

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

*Last Report, No. .... Port*

*(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case. ....)*

CHARACTER. ✱ for Special Survey, Date of last Survey and of Periodical Surveys.	Years Assigned	expired.	Machinery and Boiler Survivors (including date of N.B., if any)
100A1 (Class Contemplated)			
PF attached			

Society's Freeboard (if assigned) as }  
 painted on Ship and now verified } ..... ft ..... ins

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Lamination on the No 2 starboard hatchside*  
*coaming between No 5 web and the butt made good by means of electric welding.*

SUMMARY OF DAMAGE REPAIRS :—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed	...								
Removed and Fair'd or Repaired	...								
Fair'd or Repaired in place	...								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Souppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt	Planking	(State if welds removed)
Caulking of ditto	(State which.)	of Wood Vessels	Sails
Rivets	Rudder	Caulking	Equipment letter
Breasthooks & Crutches	Steering gear and its connections	Treenails	Anchors, No. of
Transoms	Windlass	Breasthooks & Stemson	Cables (State if now ranged)
Frames	Have Pumps not been examined and found efficient?	Transoms, Pointers, & Crutches ditto	„ length size
Reverse Frames	Have Safety Valves now been examined and found efficient?	Timbers of Frame at openings ditto	(on board)
Floors	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	„ Rule length size
Keelsons		Stringers, Clamps & Shelves	Hawser & Warps
		Salting	Standing & Running Riggings
		(State if examined.)	

*General Observations, Opinion as to Class, Recommendation, &c.:*—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

This vessel is eligible in my opinion to retain the class recommended by the Malmo Surveyors without fresh record of survey.

Survey Fee ( <del>per Section 20</del> ) .....	£ <i>2</i>	<i>30:00</i>	:		Fees applied for,
Special Damage or Repair Fee (if any) .....	£	:	:		<i>14<sup>th</sup> Oct</i> 19 <i>21</i>
( <i>per Sec. 20</i> )					
Travelling Expenses (if chargeable) .....	£	:	:		Received by me,
					19 .....
Second Surveyor's Fee (if any) .....	£	:	:		

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

FRI, 18 NOV. 1921

### Character Assigned

See memo 1.

FRI. 2 DEC. 1921

THE 30 MAY, 1920

005280-005292-0200

**Is Certificate required? If so, to be sent to**