

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

SAT. 12 NOV. 1921

Date of writing Report *11th Nov 1921* When handed in at Local Office *11th Nov. 1921* Port of *CARDIFF*

No. in Reg. Book. Survey held at *Cardiff* Date, First Survey *31st Octo* Last Survey *3rd Nov. 1921* (No. of Visits *2*)

39944 on the Machinery of the ~~Wood, Iron or Steel~~ *S.S. "Waterway"* Master

Tonnage Gross *750* Net *✓* Vessel built at *Linham* By whom *Linham Shipyard & Co* When *1921*

Registered Horse Power *✓* Engines made at *Swansea* By whom *R. & S. Evans & Co Ltd* When *1921*

No. of Main Boilers *✓* Boilers, when made (Main) *(Donkey)* Owners *(Cry & Blundell)* Port *Cardiff* Voyage *Honfleur*

No. of Donkey Boilers *✓* Steam Pressure in Main Boilers *✓* If Surveyed *Afloat or in Dry Dock* *Kill's West Dr.* (State name of Dock.)

Last Report No. *✓* Port *Cardiff*

Particulars of Examination and Repairs (if any) *Docking*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? *✓* Was a damage report made by anyone else? If so, by whom? *✓*

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *No*

Do. " Donkey " " " " *Not done for survey*

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? *✓* To what pressure were they afterwards adjusted under steam? *✓*

Did the Surveyor examine the Safety Valves of Donkey Boiler? *✓* To what pressure were they afterwards adjusted under steam? *✓*

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? *✓* , and of the Donkey Boiler? *✓*

Did the Surveyor examine the drain plugs of the Main Boilers? *✓* , and of the Donkey Boiler? *✓*

Did the Surveyor examine all the mountings of the Main Boilers? *✓* , and of the Donkey Boiler? *✓*

Has screw shaft now been drawn and examined? *✓* Is it fitted with continuous liner? *✓* or two liners? *✓* or is it without liners? *2*

Has shaft now been changed? *✓* If so, state reasons *✓*

Is the shaft now fitted new? *✓* Has it a continuous liner? *✓* or two liners? *✓* or is it without liners? *✓*

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? *1/16"*

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? *✓*

Vessel placed in dry dock, outside fastenings & propeller examined, all found in order.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,11, E.&F.S. 9,11, or L.M.C. 9,11, 12, 13, F.B., &c.)

The above is forwarded for the information of the Committee.

Survey Fee (per Section 28)..... £ : *✓* Fees applied for
Special Damage or Repair Fee (if any)..... £ : *✓* 19
(per Section 28.)
Travelling Expenses (if chargeable)..... £ : *✓* Received by me, 19


Committee's Minute *FRI. NOV. 18 1921*
Assigned *L.M.C. 10.21*

J.S. Hunter
Engineer Surveyor to Lloyd's Register of Shipping.

FRI. 2 DEC. 1921

TUE. 30 NOV. 1921

005280 - 005292 - 0202



Lloyd's Register Foundation

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to