



LLOYD'S REGISTER OF SHIPPING

Royal Mail House
Terminus Terrace

4, Canute Road, Southampton

Telephone: Southampton 20353

Telegrams: Register.

5th August, 1960.

RECEIVED

6 - AUG 1960

And

12/8

D

"ST. JULIEN" & "ST. HELIER".

Reference

The Secretary,
London.

H.

Dear Sir,


Please refer to your Memorandum of 12th July, 1960. We are informed by British Railways that the two new fan engine crankshafts have been placed on board the above ships, but are not yet fitted in place.

As the ships are at present running to schedule on service to the Channel Islands, British Railways request that the fitting of the shafts be deferred to the end of the holiday season.

In view of the fact that the new shafts are on board and immediately available it is submitted that this request might receive favourable consideration.

The shafts were made at Southampton under our survey.

Yours faithfully,


pro The Surveyors.



© 2020

Lloyd's Register
Foundation

005321-005324-0131

