

COPY

LLOYD'S REGISTER OF SHIPPING



Port ÅBO
Date 12th July, 1962

This is to Certify ^{we} that ^I have
Surveyed the M.S. MARINA, 607 tons gross of Mariehamn on the 19th
June and subsequently whilst the ship lay docked at Nystad, Finland
for Docking Survey and Repairs

^{we will}
and that I ^X ~~am~~ transmitting ~~XXX~~ to the Committee of Lloyd's Register of
Shipping, London, a Report, stating that all repairs recommended by ^{us}
^{our} ~~we~~ have been completed to ^{my} ~~my~~ satisfaction, also that ^X ~~I~~ ^{XXX} ~~we~~ are
recommending that she ^{XX} ~~be~~ remains as classed with fresh record of
DS 6/62 subject to the worn out rivet heads in shell and bottom
plating below load water line to be examined and dealt with as
necessary latest September 1962 (3 months limit).

S. J. Törnquist
S. J. Törnquist ^{Surveyor to Lloyd's Register.} ~~Ali Haidet~~

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BiS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	SS(P)	Hull Special Survey (Progressive)

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

130m,9,60 (MADE AND PRINTED IN ENGLAND.)

005337 - 005343 - 0150

