

by Chief Ship Surveyor

Received from Chief Ship Surveyor

DB 22

EL'S NAME

"DRAKE"

Rpt. Lon.

No. 100640

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey


The 1st S.S.No.3 became due 2,34 and no part of the survey has been held. (See letter 9.10.34)

The London Surveyors now report the ship placed in drydock, the bottom coated and minor repairs effected.

Nothing has been done towards the Special Survey at this time.

It is stated that the ship is to be stationed at Zanzibar and with a view to carrying Pilgrims, alterations to hatchways, etc., have been made in accordance with approved plans.

It is submitted action be deferred.



© 2021

Lloyd's Register Foundation

Handwritten signatures and the date 13.10.34.

005358 - 005366 - 0113