

Ship's name

"R A N A"

Port

GRO

No. 2565a

Last survey date 8.10.62.

Class is subject to

tank top plating of No.2 D.B. tank (s.s)
(temporarily repaired 1,62) being specially
examined and dealt with as necessary by the
Special Survey.

R.L. Appendix ~~XXXXXX~~ none)

Nature of present survey (afloat and in drydock)

Docking: Deferred repairs to grounding damage.
Wear and tear repairs.

Recommendation

SUBMITTED record of DS 9,62 be assigned,
subject as above and to indented shell plate B.5
(s.s.from fwd) being specially examined and
dealt with as necessary by the Special Survey.

DS 9,62 Subject.

NOTE:- This ship has been reported foundered
North West of Hamburg 2.11.62.



© 2020

Lloyd's Register
Foundation

D.F.C
1/1/62

005367-005376-0020