

Dear Sirs,

85

B. 2m.131.

FREEBOARD REPORT on the

Ronan Hunter, Wigham Richardson
No 1477.

*This submitted the two surveyors be requested
to ascertain from the builders the trim by
stem, if any, in service, when the vessel is
fully loaded in order that the question
of on-board scuppers and freeing ports
may be decided.*

W.S.

12.4.82

*for Mac
12/4/82.*



© 2021

Lloyd's Register
Foundation

005397-005402-0150