

1500, 10, 40. Sir James Laing & Sons Ltd. Sunderland. Yard No. 745.

F.E.

Boiler SAILOR

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "EMPIRE COLLINS" Rpt. 1 Sld. No. 33571

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No.

Depth "d"

2nd Long. No.

Proportions = $\frac{L}{D}$ 13.2 /


Framing As approved

Sheerstrake As approved

Sister vessel to the "EMPIRE AIRMAN," "EMPIRE MARVELL" & "EMPIRE COLERIDGE"

Two longitudinal bulkheads are fitted.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed as 100A1 "Carrying Petroleum in bulk" "Fitted for oil fuel 12.42 FP above 150°F"



1 Dk "Longitudinal framing" "Butts of sheerstrake electrically welded"

Cell DB u E 55' 87t, DTf 31' 613t, FPT 322t, APT 205t

FK, 13BH, Lloyd's A & CP

P 109' F 38'

Mchy aft

O.L. 503.8'

e† The class is assigned and maintained upon the understanding that the equipment will be made to accord with the requirements of the Rules when the present state of emergency has passed.

Insert in S.R.L.:- (A bower anchor and 60 fathoms chain cable to be supplied).

gates and



© 2020..... 18.1.43

Lloyd's Register Foundation

605429-005435-0153