

37088

Lloyd's Register of Shipping.

Ship's Name "SOUTHERN COLLINS"

Official No. 169106

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in

A total of 18" manholes have been cut in the upper deck for the installation of the "Butterworth" tank cleaning system. Each is closed by a bolted watertight cover plate.

A copy of this Report has been placed on board the vessel.

Alfred J. S. Shiffers
12th December, 1947.

SURVEYOR TO LLOYD'S REGISTER.
NEWCASTLE-ON-TYNE.

Noted
24 DEC 1947

Lined area for additional text or notes.



© 2020
Lloyd's Register
Foundation