

REPORT ON MASTS, SPARS, AND RIGGING.

Ship and now very

3500,9,35.

2

an

"Examined 7.46"

ACTION is DEFERRED for completion of SPECIAL SURVEY.

Recd 7/6

Sent to Chief Surveyors

Received from Chief Surveyors

23

VESSEL'S NAME

"MARWARRI"

Report

Gls.

No. 72683

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

(C)

(PERIODICAL ~~NO.~~ SPECIAL SURVEY/PARTLY HELD.

Cal. 8.47) Damage -
Conversion to oil fuel

When due

When proposed to be completed

Portion of Survey held, &c.

All items.

NOTED

3.48 Gl.s.)
"S.S. Gl.s. 3.48") without.

Insert in R.B.

"Fitted for oil fuel 3.48
F.P. above 1500F".

ABM.
16-4-48.
BAM



© 2020

Lloyd's Register
Foundation

005436-005442-0040

To the Surveyors,

Lloyd's Register of Shipping.

Standing and Run

Sails