

COPY

Lloyd's Register of Shipping,

High Close, Wokingham, Berks.

ENCLOSURES

6th May, 1942.

Dear Sir,

S.

I enclose Liverpool Report No.117603 on the Steamer "EMPIRE AIRMAN" which was recently completed at Sunderland and think it well to draw attention to the remarks regarding the sternframe which was found fractured at the top of the rudder post, and to the repairs shewn on the plan attached to the report.

I shall be obliged if you will bring this case to the notice of the C.S.S. Department as it may be considered desirable that the Sunderland Surveyors should be informed with a view to action being taken regarding the sternframe in any projected sister or similar ships.

It is also thought well to enclose a letter, with blue print attached, which has been received from the Sunderland Surveyors respecting reinforcements fitted in a later sister ship, the "EMPIRE MARVELL".

It will be appreciated if you will return the enclosed documents in due course.

I am, Dear Sir,
Yours faithfully,

pro Secretary.

The Secretary,
C.S.S. Department,
GLASGOW.



© 2020

Lloyd's Register
Foundation

005436-005442-0174

Special Damage or Repair Fee (if any).....£
(per Sec. 29)

Travelling Expenses (if chargeable)£

Received by me,

19

Geo. L. Kyle & Co

Secretary to Lloyd's Register