

COPY.

# Lloyd's Register of Shipping.



Port San Nicholas, Aruba, N.W.I.

July 3rd., 1941

**This is to Certify** *that I have*

*Surveyed the Boiler and <sup>Part</sup> Machinery of the M.V. "CARIPITENO",*

*475 gross tons of Cristobal Colon, on account of drydocking,  
tail shaft survey and +L.M.C. (M.) survey,*

*and that I have transmitted to the Committee of Lloyd's  
Register of Shipping, London, a Report stating that all  
recommendations made by me in connection therewith have  
been carried out to my satisfaction, and that I have*

**Recommended** *that the records of Tail Shaft seen 6-41 and  
+L.M.C. (M.) 7-41*

*be made in the Register Book in the case of this vessel, subject  
to the Tail Shaft being renewed within six months i.e. before  
the end of December 1941.*

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."