

[Thin Copy for attaching to Report.]

4a.

COPY

Lloyd's Register of Shipping.

Port San Nicholas, Aruba, N.W.I.

July 3rd., 1941

Dear Sirs:


With reference to the
Survey now being held on the ~~Steamer~~
M.V. "CARIPITENO"

I beg to inform you that, in consequence of
the condition of this vessel's Tail Shaft

it will be my duty to recommend to the Com-
mittee that the same be renewed
before the end of December, 1941
as provided for in the Rules, extracts from
which appear on the other side:—the con-
tinuance of the vessel's character in the
Society's Register Book to be subject to the
due fulfilment of this condition.

I am,

Yours faithfully,


Engineer Surveyor to Lloyd's Register.

To Messrs. Lago Shipping Co., Ltd.

San Nicholas.

11.34.

MADE IN ENGLAND.

9600-785500-62800
005824-005536-0076

Lloyd's Register
Foundation