

COPY FOR LONDON OFFICE.
Lloyd's Register of Shipping.

PROVISIONAL RE ENTRY INTO LLOYD'S CLASS.

Port Sydney, N.S.W.

24th January 1925.

This is to Certify that I have

Surveyed the Steel Screw Steamer

"U N A" of Melbourne.


in Morts Slipway and afloat at Sydney N.S.W.

and that I have transmitted to the Committee of Lloyd's Register
of Shipping, London, a Report, as on the other side, stating
that all repairs recommended by me have been completed to
my satisfaction. See continuation sheet.

(SGD) A. C. HERON.
" b" Jas. C. ERSKINE.

Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood
that the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or
issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of
default, or negligence of the Surveyors, or other Officers or Agents of the Society.



© 2021

Lloyd's Register
Foundation

005625-005643-0095 1/2

COPY

T.S.S. "U N A" EX "KOMET"

TO COMPLETE THE SURVEY:-

Lift ceiling in No. I Hold.

Test with water all double bottoms and both Peaks.

Air and sounding pipes to examine.

Repair No. I Hatch coaming angles.

Lifeboats to see in good order.

Clean and scale side bunkers.

Mast and Bowsprit wedges and Rigging to examine.

Supply 1st Bower Anchor with certificate.

Supply Stream Anchor with certificate.

Supply 60 fathoms of $3\frac{1}{2}$ " steel wire with certificate in lieu of Stream Chain.

Supply 90 fathoms of $3\frac{1}{4}$ " steel wire tow line with certificate.

Examine and test fresh water tanks abaft Engine Room.

Examine ships side in way of insulation cold chambers.

Supply London Signal letters and Official Number.

Melbourne Surveyor advised.

(SGD) A. C. HERON.
" Jas. C. ERSKINE.

SURVEYORS TO LLOYD'S REGISTER.



© 2021

Lloyd's Register
Foundation

005635-005643-0095 2/2