

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Vic. 79.

Rpt.

Sps.

mdh

No. 112569
17658

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

COMPOUND.

N.H.P. 24.

If Boilers fitted with forced draught

no

Tail Shaft. If fitted with a continuous liner

no

If fitted with an outside gland of

approved type

yes

This vessel's machinery ~~appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed~~ L.M.C. 2.45

YR

8. 3. 45



© 2020

Lloyd's Register Foundation

005756-05778-0296

The question of how gear is under consideration with the Admiralty. See correspondence attached to Vic 49.