

Lloyd's Register of Shipping.

Royal Bank Buildings,
28, Constitution Street,

✓ LLOYD'S REGISTER,
LONDON.

Leith,

18th. July, 1918.

RECD JUL 19 1918


AN82

Dear Sir,

In reply to your classing letter of the 16th. inst.
"WAR PIBROCH", and with regard to enquiry contained therein,
I beg to state that a semi-box beam was fitted on the fore side
of the collision bulkhead on the lower deck stringer of the
following size:- plate .48 x .306 connected to bulkhead by
3½ x 3½ x .35 angles and beam on fore side 8 x 3 x .42 Bulb
Angles, as required, ~~but that the Poop Deck was not sheathed~~
with wood. 1½" lining fitted between the beams below the deck
as per instructions from D.C.A.S., letter dated 17th. Feb. 1918,
also letter from S.P. Austin dated 27th. Mar. 1918.

I am, Dear Sir,

Yours faithfully,



The Secretary,

L O N D O N .



© 2020

Lloyd's Register
Foundation

005791-005810-0325

Referred to the Chief Engineer Surveyor.

SECRET & CONFIDENTIAL

Referred to the Chief Ship Surveyor.

Handwritten initials

JUL 19 1898

Also for Mr. S. A. Bill to note

Handwritten signature

Vertical handwritten text



© 2020

Lloyd's Register
Foundation