

For the information of Surveyors and the Committee only.

Received at _____ Office, _____ 19__

Lloyd's Register of Shipping.

(Report on Vessel No. _____ Port _____)

No. 76 SHIP ~~FORGINGS OR~~ CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~ manufactured by The Columbia Steel Company of Pittsburg Cal. for the Vessel No. 1642, being built by The Skinner & Eddy Corp. of Seattle Wash. have been inspected by me as set forth below and found to be, so far as can be seen, sound.

Stern frame in two sections.

*R. B. Batchelor.
San Francisco.*

on Forgings or Castings.

Lloyd's
No. 76
RB. 1/17

	STERN FRAME.	RUDDER FRAME.	STEM.
Material	<i>W. Steel.</i>		
Made	<i>Cast.</i>		
Dimensions	<i>As per plan.</i>		
Process on Inspection	<i>Cast.</i>		
When Inspected	<i>Dec 27/16. Jan 3rd 9th + 12th /1917.</i>		
CASTINGS. on Standard Test Pieces.	<i>upper</i>	<i>lower.</i>	
Tensile Test— per square inch	<i>60800.</i>	<i>63500</i>	
Elongation per cent.	<i>31.</i>	<i>30</i>	
Bending Test— angle before fracture	<i>120°</i>	<i>120°</i>	
Height from ground	<i>7 feet</i>	<i>7 feet</i>	
Welding Test— made according to Rules and found satisfactory	<i>Yes.</i>	<i>Yes.</i>	

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.



© 2021

Lloyd's Register

Foundation

Fee (if any chargeable) £ 25.00
Expenses. \$ 2.67
To be paid at SAN FRANCISCO.

of Iron, state whether scrap or puddled Iron. If of steel, state whether made on the Open Hearth process.