

Steel Screw Steamer "ASTOR"

6561 tons gross; Built in 1917

Classed: * 100A1
Shelter deck with
1,23

Cargo Bittens not fitted in tween decks

63671 in the Register Book;

2 mo.; Port of Registry - Savona;

* LMC 4,20
BS 1,23
TS 1,23.
Water Tube Boil

The First Special Survey No.1 became due in February last.
Survey of the Water Tube Boilers in January last

Steel Screw Steamer "GIGLIO"; No.70687 in the Register Book;

3160 tons gross; Built in 1917 - 12 mo.; Port of Registry - Sa

Classed: * 100A1
12,23
s.s.No.1-23.

* LMC 3,23
* NE 11,18
TS 3,23.

The Annual Survey of the Boilers became due in March last.

Steel Twin Screw Steamer "PRIMULA"; No.80543 in the Register Book;

2311 tons gross; Built in 1921 - 7 mo.; Port of Registry - Savona;

Classed: * 100A1
5,23

* LMC 2,23
TS 5,23
Oil Engines

OWNER: Edoardo Mazza


Correspondence has for some time been taking place between this Office and the Society's Surveyors at Genoa regarding an intimation received in March last from the Owner, at Savona, that he had decided to allow the classification of his vessels with this Society to lapse.

The Genoa Surveyors have had several interviews with the Owner, in which they have called attention to the arrangement which obtains between the Registrar of Lloyd's Register, and an effort was made to arrange a synchronisation of the dates of survey in the two

The Owner has now informed the Genoa Office that while he appreciates the steps taken in the past he adheres to the decision to withdraw the vessels from Classification. He adds that in February last he is ensuring the utmost economy while maintaining

© 2021

Lloyd's Register
Foundation



1. 2670 - Savona - 08/07/20

(2.

Registro Italiano and a British Classification Society, preference was given to the British Corporation on account of the small additional fees chargeable, namely 10 per cent. of the Registro Italiano classification fee.

The cases of these vessels came before the Classing Committee on Tuesday, 26th instant, when it was decided to withdraw the class of each steamer from the Society's Register Book and to insert three dots (...) in lieu thereof, indicating withdrawal of class at Owner's request.

FAM

28th August, 1924.



© 2021 0292 3/3

Lloyd's Register
Foundation