

2m, 10, 3.

to Chief Surveyors.....

Received from Chief Surveyors.....

24. 3. 44

SEL'S NAME "COLLINGWOOD"

REPORT Lon.

No. 111467A

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey.....

When due.....

In reply to enquiry the Owners state they do not desire the Classification of this vessel to be continued in the Society's Register Book.

It is submitted the class of this vessel be withdrawn from the Register Book and 3 dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class
Insert (...)

CAH

J.F.

23. 3. 44



© 2020

Lloyd's Register
Foundation

006407-006411-0034