

*Bauka*

TELEPHONE: SACKVILLE 906

LLOYD'S REGISTER OF SHIPPING

LLOYD'S REGISTER  
LONDON.  
REC'D 16 MAY 1920  
ANS'D ✓

~~EXAMINED WITH NO LANDING~~

~~HALIFAX, N.S.~~

New Glasgow, N. S.,

May 28, 1920.

~~E. Carey, Esq.,~~  
Ass't to <sup>T</sup>he Secretary,  
Lloyd's Register of Shipping,  
71 Fenchurch St.,  
London, E.C.

Dear Sir:

I am in receipt of your favor dated  
April 20th., with two certificates for the S.S. "CANADIAN SEALER".  
The lower stiffeners on after peak bulkhead are spaced 24" apart  
as approved. Fuses are fitted on the main switchboard of the  
cables of main circuits. This applies to the S.S. "CANADIAN  
MINER" also.

I am, Dear Sir,

Yours very truly,

*A. Jones*



© 2021

Lloyd's Register  
Foundation

006435-006446-0053



Referred to the Chief Ship Surveyor,  
and the Chief Engineer Surveyor.

CSA

16 JUN 1920

Also for Mr. S. A. Hill to note.

M  
16/6/20

Noted.  
HYP  
16/6/20



© 2021

Wood's Register  
Foundation