

1

Disel 57

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME **STEEL S.S. "LIBERTY LAND"** Report **Phl.** No. **3390**

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24532.)

Nature of Survey

When due

Kedge Anchor Tested by American Bureau Surveyors.

Chain Cables of Cast Steel, tested as required.


100 A.1. (steel)

2 Dks (steel) and Webframes.

Cell OB 275' 1380t. MT 24' 748t. FPT 144t. APT 100t.

FK. 8 BH. Cam. A & C.P P 35', B 122', F 43'

It is concluded, the bulkhead stiffeners are as approved but the Surveyors should be requested to state if this is so.



Lloyd's Register
Foundation

006479-006488-0264

at 3. 3.10.19