

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

"PURIRI"

Report

Lon.

No.

108410

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

No surveys are due on this vessel.

In reply to inquiry regarding the adoption of the Continuous Survey arrangement as regards the oil engines, the Wellington Surveyor now writes stating that the Owners do not wish to keep the vessel in class.

It is submitted the class of the vessel be withdrawn from the Register Book and Three Dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class.

Insert...



© 2020

Lloyd's Register
Foundation