

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book 62165 Survey held at on the Wood, Iron or Steel & ADIGE Date, First Survey Last Survey 1910 12 19

TONNAGE: GROSS 6543 UNDER DECK 6261 NET 3922 Built at Chepstow By whom Monmouth S.B. Co. Ltd. Owners Kauffahrt & Co. Managers Owners' Address Port belonging to Bremen

Surveyed Afloat or in Dry Dock? Name of Dock WB=CellDBorDBa feet; u&B feet; f feet total capacity tons. FPT tons; APT tons; MT feet tons. Destined Voyage Particulars of Classification

N.B.—All alterations in the existing records should be underlined. If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined.

Last Report, No. 9097 Port Gen

Table with columns: CHARACTER, Date of last Survey and of Periodical Surveys, Machinery and Boiler Surveys. Includes classification codes like +100A, shelter Dk, with freeboard, 8.25, ss. Gen. No. 1-24, Cargo battens not fitted in green WTB decks.

Special Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs due to other causes; besides being detailed in the body of the report, should be summarised in the form shown below.

Where cases where the Surveyor has not made a special damage report he is required to state whether he has declined his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Table: TYPE OF DAMAGE REPAIRS:— Shell Plates, Frames, R. Frames, Floors, Beams, Str. Plates, Dk. Plates, Other Items:—

Table: CONDITION OF THE... State if Tanks have been examined inside, State if Tanks now tested, Bulkheads, Ceiling, Cement or Asphalt, Rudder, Steering gear and its connections, Windlass, Have Pumps now been examined and found efficient?, Have Sluice Valves now been examined and found efficient?, Have Watertight Doors now been examined and found efficient?, Have Ventilators and their Coamings been examined and found efficient?

### General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24 and ptND24, &c."

Table: Fees applied for, Received by me. Includes Surveyor's Fee, Expenses, etc.

Committee's Minute TUES. 18 JAN 1927

Surveyor Assigned... withdraw class & insert ( )

Surveyor to Lloyd's Register of Shipping. General Committee Thursday, 20th January 1927. Classing Committee's Register decision confirmed

1910-657900-645900  
Is Certificate required? If so, to be sent