

Messrs. Cochran & Co.
Boiler No. 14212.

Gr. No. 60740.

It is submitted that before this
 case receives consideration the Gr.
 Surveyors should be requested to verify
 their statement that the longitudinal
 joint in the shell is double riveted,
 as single riveting is shown in the
 plan.

Lr 1/3



© 2021

Lloyd's Register
 Foundation

006797-006808-0236