

s/c "Manxsona"

Ips. 83439

It is submitted the Ipswich Surveyor should be requested to state whether the screw shaft is fitted with a continuous liner the whole length of the stern tube.

JWD
6/2/04