

Report to Chief Surveyors.....

Received from Chief Surveyors..... **6 AUG 1941**

SHIP'S NAME MARY Report GLS. No. 64126

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Subject of Survey DAMAGE AND EXAMINATION OF GERMANISCHER LLOYD CLASSED DUTCH VESSEL FOR
ASSIGNMENT OF EXAMINED L.R.

The bottom plating in way of N°2 hatchway requires to be faired at the first convenient opportunity.

WAS
6.8.41

Insert for S.R.L.
L.R.
"Examined 7.41 - 12 months"
+ as above

Docking date 7.41
gld



© 2021

Lloyd's Register
Foundation

007059. 007071 - 0007