

DISCLOSED SECTION

SECTION

Rpt. 8.

(Received at London Office)

No. 117421 A

# REPORT of SURVEY for REPAIRS, &c.

No 435

24 AUG 1949

Date of writing Report.....19..... When handed in at Local Office.....19..... Port of Genoa LONDON

No. in Survey held at on the Wood, Iron or Steel Date, First Survey ss. ANGELICA Last Survey 9 Sept 19

TONNAGE:— Built at Newcastle By whom Armstrong, Whitworth & Co Ltd When 1918 YEAR MONTH  
GROSS 3149 Owners Soc. di Nav. Samei Owners' Address  
UNDER DK. 2866 Managers Port belonging to Genoa  
NET 1846

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage  
WB=CellDBorDBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted  
total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.  
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 5479 Port Ris

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned how long expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+100A1		+LMC 6.48
4.49		TS 1.48 cl
SS.Hpl. - 6.48(Dc.)		
Cargo ladders not fitted.		

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined  
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt). When put on, Month Year
Caulking of Decks	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats
Coamings	Ceiling	Scuppers	Masts, Yards, &c.
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Condition, how ascertained.
Outside Plating	Rudder	Hatches	(State if wedges removed)
Breasthooks	Steering gear and its connections	Planking of Wood Vessels	Sails
Transoms	Windlass	Caulking ditto	Equipment letter
Frames	Have Pumps now been examined and found efficient?	Treenails ditto	Anchors, No. of
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stems ditto	Cables (State if now ranged)
Longitudinals	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	length size (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Rule length size
Floors		Ditto ditto at other places ditto	Hawser & Warps
Keelsons		Stringers, Clamps & Shelves ditto	Standing and Running Rigging
Stringers		Salting ditto (State if examined.)	
Inner Bottom Plating			

General Observations, Opinion as to Class, Recommendation, &c.:—  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute  
Character Assigned  
Write Gofw  
FRI 9 SEP 1949  
with draw class & insert (...)  
Surveyor to Lloyd's Register of Shipping.  
Lloyd's  
General Committee  
Thursday, 22nd September 1949  
Classing Committee's decision confirmed N66

007257-00765-019

Is Certificate required? If so, to be sent to