

007257-007268-0163

Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "B.C.SURVEYOR" (ex "Leola Vivian") REPORT Lon. No. 115240a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey..... When due.....

¹⁰¹⁰
9A1 and holds notation of "Laid up pending Survey".

The VANCOUVER Surveyors state in a letter dated the 15th July 1947, that it is not the Owners' intention to retain this vessel in the Society's classification.

It is therefore submitted the class of this vessel be expunged from the Register Book and a red line (—) inserted in lieu, indicating non-compliance with the Society's Rules as regards surveys.

Delete class.
Insert (—7.47—)



© 2021

Lloyd's Register
Foundation

Handwritten signature
4-9-47

Handwritten initials
6/2/16