

offered his services for this purpose and to whom and why they were declined

2m 3,40.

t to Chief Surveyors.....

Received from Chief Surveyors.....

8 SEP 1947

SSEL'S NAME VIC 81 REPORT Lon. No. 115247A

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey..... When due.....

A communication dated 25th August 1947 has been received from the Director of Stores, Admiralty, which states it is not desired that this vessel should remain in classification.

It is accordingly submitted the class of the vessel be withdrawn from the Register Book.

Withdraw Class.

Met
14-9-47.
LB.



© 2021

Lloyd's Register Foundation

007528-007536-0090