

COPY.

Lloyd's Register of Shipping.

Preliminary Certificate No. C.352.

Port of P R A G U E,

2nd May, 1930.

Order No.513...3.3.30, D.M.F.No.1565.

Skoda Com.No. 78-06.2502/3.

This is to Certify that

Ing. P. Kertscher,

the undersigned Surveyor to this Society did at the request of Messrs.Limited Co.formerly the Skoda Works, attend at their works in Pilsen, Czecho-Slovakia, on the 28th March,1930, and subsequent dates in order to inspect in black forged condition and mark the necessary test pieces of the undermentioned forgings, intended for built-up crankshaft, ordered by Messrs. Deutsche Bussan A.G., Berlin, for Messrs. Uraga Dock-Yard Company, Ltd., Uraga, Japan, Ship No.374:

Description.	Skoda Forging No.	Charge No.	Test No.
5 cranks	3705-6-7-8-9	42586	356 a,b,
2 "	3753-4	42655	369 a,b,
4 "	3806-7-8, 3875	42570	370 a,b,
6 journals	3797-8-9, 3800-1-2	42756	371 a,b,
4 end journals &			
2 journals	3760-1-2-3-4-5	42686	372 a,b,

The forgings were smooth, made from sound ingots, and have been gradually and uniformly forged. They have been thoroughly annealed according to the usual practice of Messrs. Limited Co.formerly the Skoda Works. The various parts are being marked with private stamps for identification during the course of manufacture.

Ing. P. Kertscher.

Surveyor to:

Lloyd's Register of Shipping, Prague.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.