

10

State latest date of internal examination of each boiler

4 E

Inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

"COTENTIN".

Rpt.

Hav No.

8138.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/6/02.)

Reference of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

New screw shaft fitted to accommodate new propeller.

It is submitted the vessel is eligible to remain as classed with notation S(N)5,39.



© 2020

Y Rub

Lloyd's Register
Foundation

31.5.39.

007714-007721-0251

Satisfactory.