

to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME SH Se MIRANI

Report Sls

No. 47865

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 21.5.92.)

Nature of Survey

P. Entry

When due

Revised Rules

✠ 100A.1. (Steel)

1 D¹ (Stl - ws). Well D¹

Cell D.B a.v E H 4' + 84' 1885, F.P.T. 155, A.P.T. 206

F.K. H B.H., Cem, Clayds A CP

Q 46', B 55', F 29'.

Am Junc
A/49



© 2020

Lloyd's Register
Foundation

007958-007966-0091