

"MARY SWEENEY"

F.E. Rpt. St.J.. No. 1036

It is submitted before this case receives consideration the reply from the NEW YORK Office regarding the service limits be awaited.

It is further submitted the SAINT JOHN Surveyors be requested to furnish the soundings of the single bottom in the Machinery Space and to state the position of the W.T. Bulkheads extending to the Upper deck.

They should be informed it is concluded the length of the double bottom is 71.5' and not 79.83' as reported, but this should be confirmed.



© 2021

Lloyd's Register
Foundation

008028-008079-0078