

(Letter for record

S ✓

Total Heating Surface of Boilers

634 #

Is forced draft fitted

sp "bento."

Sld. Rpt. No. 25058.

It is submitted, that the Sunderland Surveyors should be requested to state, whether there are sluices on the Engine room bulkhead, & also the number of the main boiler test certificate, omitted from their report.

not to be kept

ck for this enquiry

JWR

Ln. 24/11/11

JWR

20/11/11

JWR

Lloyd's Register Foundation

008068-008078-0161

Top // X10 If stays are fitted with nuts or riveted heads

nuts

Working pressure by rules 100 lb Mater