

Floyd's Register of Shipping.

Port of Survey *Liverpool*
Date of Survey *Sept 19 32*
Name of Surveyor

CONNECTED WITH
Wien Jurko Tonic

Ship's Name. TURRO TOPIC		Port of Registry and Nationality. Yugoslav Susak		Official Number. ✓	Gross Tonnage. 3415 ✓	Date of Build. 1911-11	Particulars of Classification. + 100 A1	
-Number in Register Book								
Registered dimensions from Ship's Register.	LENGTH. 348.3	BREADTH. 50.2	DEPTH. 23.6	UNDER DECK TONNAGE. 3439.94	Moulded Depth as measured..... 25-11½			NOTE.—If the depth is measured when vessel is afloat, the details of measurement should be reported.
Length on LOADLINE.	347.8	MEAN Frame Depth $4\frac{1}{4}$ Rule „ $5\frac{1}{2}$ $4\frac{1}{2} \times 2 \times 2\frac{1}{4}$ Sparring fitted -37	Ceiling fitted Sheer + 1.00 Yank top level	Peak Tanks } Includ.	Addition for Keel below base line for draught record.....inches.			
CORRECTED DIMENSIONS.	347.8	49.83	24.60	3439.94	CORRECTION FOR LENGTH.			
Co-efficient of fineness..... .80								
Any modification necessary } - .02 C.D.B. [Para. 4 (a) to (e)]*								
Co-efficient as corrected78								
CORRECTION FOR IRON DECK.								
Proportion covered, if less than $\frac{7}{10}$ this length covered4308								
Thickness of usual wood deck, less stringer 3½ - $\frac{1}{2}$								
CORRECTION FOR ROUND OF BEAM.								
Breadth at Gunwale amidships..... 48-10½								
Round of Beam 12								
Normal round..... 12¼								
Difference $\frac{1}{4} \div 2 =$ ⅛								
Proportion of Deck uncovered (Para. 19)								
Freeboard, Table A 5-11¼								
Correction for Sheer 8¾								
Correction for Length 5-2½								
Allowance for Deck Erections 8								
Correction for Round of Beam..... 4-11½								
Correction for fall in Sheer (if any)..... ✓								
Correction for Steel Deck (if required) 1½								
Additions for non-compliance with provisions of } 4-10 Para. 11 (d) and (e)†								
Other Corrections (if any) ✓								
Winter Freeboard 4-10								
Summer Freeboard 4-5¾								
Indian Summer Freeboard 4-1½								
N. A. Winter Freeboard								
Correction necessary because clearside amidships, measured in accordance with the Statute is not taken at the intersection of the wood or steel deck with side.								
Winter Freeboard from deck line								
Summer " " " "								
Indian Summer " " " "								
N.A.Winter " " " "								

SUMMER FREEBOARD amidships from Centre of Disc to top of Deck Line, ~~Wood~~, Steel, Deck:—

Tropical Fresh Water Line above Centre of Disc	...	10 1/2 = 266	Tropical Fresh Water Freeboard	...
Fresh Water Line	"	6 = 152	Fresh Water	"
Tropical Line	"	4 1/2 = 114	Tropical	"
Winter Line	below	4 = 102	Winter	"
Winter North Atlantic Line	"	✓	Winter North Atlantic	"

16 SEP 1932

16,32. 14 MAR 1936

MARKING FORM

- 3 SEP 1934 FW

$$\frac{8585}{40} \times 35 = 6.1 = 6$$

MARKING FORM

RECEIVED



Lloyd's Register
Foundation