

LLOYD'S REGISTER,
LONDON.

REQ 14 AUG 1923

AN80

H.M. DOCKYARD,

SHEERNESS.

13th August, 1923.

Gentlemen,

The Oil Tanker "WAR HINDOO" has sustained damage above water owing to collision with a tug at Antwerp.

The repairs to the vessel are ordered by Admiralty to be executed by Sheerness Dockyard, but before the ~~work~~ work is commenced it is desired that a Lloyds Surveyor may attend at this Yard to consult as to the extent of the repairs necessary.

The vessel is now lying off Sheerness Dockyard and I should therefore be glad if you will inform me of the earliest date and time the surveyor may be expected.

Yours faithfully,

at Buckhouse

CAPTAIN SUPERINTENDENT.

K.H.
C.C.

~~N.S.O.~~

The Secretary,
Lloyds Registry of Shipping,
71 Fenchurch Street,
L O N D O N.



© 2021

Lloyd's Register
Foundation

9500-560800-680800

E.S.E.P.

Referred to Mr. Carey.
Referred to Mr. S. A. Hill.

14 AUG 1923

C.H.

(Wednesday)

Tomorrow morning 9 o'clock from Victoria.

P.K.
14/8/23



© 2021

Lloyd's Register
Foundation