

AR

TELEPHONE B 7506

# LLOYD'S REGISTER OF SHIPPING

36 FURNESS WITHY BUILDING,  
HALIFAX, N. S.,

August 28th, 1944.



The Secretary,  
Lloyd's Register of Shipping,  
High Close,  
Wokingham, Berks.

Dear Sir:

We are in receipt of your letter (S) of the 1st inst. respecting the steamer "CONFEDERATION PARK" and have to advise that the equipment number is 23208, letter U. The dropped weights of the anchor heads and shanks were as follows:-

	Head	Shank	Surveyors initials	No. of Certificate	Date
1st bower	3370 lbs.	1624 lbs.	H.G.L.P.	1990	28-2-44
2nd bower	3364 lbs.	1628 lbs.	H.G.L.P.	2432	30-3-44
Stream	900 lbs.	573 lbs.	H.G.L.P.	2431	30-3-44

You will observe there is a deficiency in the weight of the stream anchor and the London office was notified from Montreal for the reason of same.

It is noticed that a typographical error was made in the weight of the 2nd bower anchor, which should read 5298 lbs. and not 5289 as stated. We shall be obliged if you will correct the Report accordingly.

*This applies to the "AVONDALE PARK" f.c.R.*

We are, Dear Sir,

Yours faithfully,

Surveyor.



© 2021

Lloyd's Register  
Foundation

L.C.D.

H  
R.S.

E2 OCT 1944

M

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED



© 2021  
Lloyd's Register  
Foundation



RECEIVED