

5m, 9, 35.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Screw "DORSET COAST" Report Gls. No. 57496

**For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry When due --

\*100A1 With Freeboard

1 Dk & Shelter Dk.

Cell. DB 154' 219t, FPT 65t, APT 28t.

FK, 3 BH (Coll. BH to Shelter Dk., 2 BH to 2nd Dk.) Cem., Lloyd's A & CP

F 23' Baft 33'

Machy. aft.


Extreme breadth over belting 34' 10 $\frac{1}{2}$ "

Sister ship to the "DEVON COAST" & Antium Coast

Date 29.10.36.

re, Angle, }

009201-00820-0128



© 2020

Lloyd's Register  
Foundation