

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME "FUSIJAMA" Rpt. Tri. No. 12883

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

The class is subject to indented keel and bottom plating forward being dealt with at the Owners' convenience.

*Tri 10002*

The Trieste Surveyors report the vessel placed in dry dock, the bottom coated and 2 stem plates repaired.

The indented keel and bottom plating as above continues efficient.

It is submitted the vessel appears worthy to remain as classed with record of survey 4.40, subject as above.

100A1 )  
4.40 Tri ) Subject, etc.

*[Handwritten signature]*



© 2021 9.5.40

Lloyd's Register  
Foundation