

22 AUG 1938

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME "TREMMEADOW".

Rpt. Bry.

No. 23754.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

E.W. 5,38

The class is subject to the repair to the solepiece of the stern frame port side, being examined at the next dry docking.

In connexion with the classification of this vessel with the Registro Italiano also, the Barry Surveyors report the vessel placed in dry dock, bottom coated and a General Examination made with satisfactory results.

It is submitted the vessel appears worthy to remain as classed with fresh record of survey 8,38, subject as above.

100A1)-subject etc.
8,38 Bry)

[Handwritten signature]
[Handwritten signature]
17.8.38



© 2021

Lloyd's Register
Foundation