

5 AUG 1948

Received from Chief Surveyors.....

Gen.

No. 16192

REPORT

~~SHIP~~ ENGINEER SURVEYOR.

ment to contain a succinct summary of any repairs that have been
not clearly any exceptional features in connection with the case
to endorsement."—(Extract from Sub-Committee's Report, 24 / 5 / 92.)

When due.....

For the CHIEF SHIP

cases which have to be submitted to the Classin
equivalent and to show the cause or causes of such
to the Classing Committee may have all the r

ature of Survey.....

For conditions see previous endorsement.

The last notation of Special Survey is No. 1-36, but
the validity of an "Examined" notation expired 6.48.

A Periodical Special Survey (D) commenced by examination
of bottom and rudder in drydock.

In the same Report the Surveyors advise change from
Panamanian to Italian Owners, who desire to let the classification
with this Society lapse, and only retain the Registro Italiano class.

This case is submitted for the consideration of the
Committee.



© 2020

Lloyd's Register
Foundation

008409-008416-0058