

1500,12,25.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor 25 JUN

VESSEL'S NAME Stl. Sc. "U3 NORTH" n/n "AJASA" Rpt. Inv. No. 80468

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey _____

The Newcastle Surveyors report this vessel placed in dry dock, bottom cleaned and coated.

It is understood the vessel has been sold to the Nigerian Government.

Alterations are being carried out to the midship deckhouses and the Owners Representatives stated no further survey would be required as it was not intended to continue the classification of the vessel.

The Surveyors forward a letter from the Owners Representatives stating they have received instructions from the Crown Agents for the Colonies to the effect that the vessel will not be continued in class.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu indicating withdrawal of class at the Owners' request.

Withdraw class.

Insert ...

[Handwritten signatures and initials]

24.6.36.



© 2020

Lloyd's Register Foundation

008492-008506-0186

008492-008506-0

or I.M. of Wood Ves
(see on Felt.)
put on, Mouth

ards, &c.

how

seed

ster

ran

gin

lk o
to

ral
rister o

be

ession