



"JULIAN"Rpt. Mmo. No. 2189.

IT IS SUBMITTED action be deferred pending receipt of the final report after satisfactory testing of steering arrangements and windlass under working conditions.



10.1.44.

© 2020

Lloyd's Register  
Foundation

008533-008540-0189