

[Thin Copy for attaching to Report.]

Lloyd's Register of Shipping.

Port..... H A M B U R G .

6th May, 1953.

Sirs,

With reference to the
now being held on the Steamer
" A T H E N S "

to inform you that, in consequence of
condition of this vessel's metallock
on the HP cylinder jacket

it will be my duty to recommend to the
that the same be re-examined & dealt with
as found necessary
the end of November 1953

as provided for in the Rules, extracts from
appear on the other side:—the con-
of the vessel's character in the
Register Book to be subject to the
alterment of this condition.

I am,

Yours faithfully,

Robert Ferguson
.....
Engineer Surveyor to Lloyd's Register.

Lloyd's Register of Shipping Col., Ltd.,
6, Bevis Marks,
London, E.C.3.

008541-008549-0106