

211 OCT 1959

Received from Chief Ship Surveyor

S NAME "DUNN" REPORT H.Kg. No. 15033

VC

standing Conditions of Class: SUBJECT to 2 15 fathom lengths of chain cable being replaced at the earliest opportunity.

L. Appendix. (As before ~~or None~~)

re of Present Survey: (~~At least and~~ in dry dock)

Docking; Supply and verification of 30 fms. of chain cable.

mmendation:

SUBMITTED record of 'DS 8.59' be assigned as recommended, WITHOUT special condition.

DS' 8.59. WITHOUT.

IN S.R.L. APPENDIX.

Bottom plating slightly wayed.  
Indents in shell plating (p & s)

OFFICE NOTE.

Bottom stiffened.  
Inner bottom plating in Nos.  
3 & 3A holds stiffened.



© 2020

Lloyd's Register  
Foundation

*Jan*  
13/10/59

008597-008607-0235