

Submitted the Surveyor be informed
the certificates could, as in previous
similar cases, be accepted for the
Chain cables and for the spare bowser
Anchor without further testing of these items

The notation of Lloyds A + CP. will however
be withheld.

CLM

28.8.47.

© 2021

Lloyd's Register
Foundation

008641-008647-0181