

7 - NOV 1945

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

S NAME "SAINTE BERNADETTE" REPORT ~~111455~~ No. ~~111455~~

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This vessel was built in July 1924 and classed  
 2100A1 "Carrying wine in portable tanks".

In 1942 the requirements of a SPECIAL SURVEY No.3  
 were carried out at Marseilles and notation of S.S. No.3-3,42 was  
 assigned.

It was then required that the plating should be  
 drilled when the vessel was 24 years old or at the next Special  
 Survey thereafter.

The Committee gave instructions on the 28th March  
 1944 that her character should be omitted from the reprint of the  
 Register Book.

<sup>stating</sup> Mr. van-Dam, Algiers, has handed in a letter from  
 the Owners that they desire reclassification.

It is understood from Mr. van-Dam that the vessel  
 has been submerged and is in a very dirty condition. He ~~desires~~ desires  
 authorisation to carry out the requisite Reclassification Survey.

In order that the vessel's class be reinstated in the  
 Book it will be necessary for the requirements of a S.S. No.3  
 to be carried out with and any portion of the structure showing evidence of  
 corrosion to be drilled in order to ascertain the thickness of the

If the Surveyors deem it necessary the shell plating  
 to be drilled as required by the Rules in which case the notation  
 No.3 with date could be assigned.

Full particulars of the equipment on board should be  
 and any structural alterations which may have been effected  
 class lapsed.

It is submitted the Surveyor, Mr. vanDam be informed  
 fully and authorised to carry out the Survey and in view of its  
 that great care should be taken in carrying out the

It is further submitted the Surveyor be informed that  
 thicknesses of the shell plating as <sup>given</sup> in the First  
 are as follows:- A,B,C,D & E strakes .43 amidships to .38"  
 .44 amidships to .38 at ends, G strake .50 to .38 at  
 (main deck ~~the~~ sheer) .60 to .38 at ends, R.Q.D.  
 .38 at after ends.

all be calling  
 on the letter

Lloyd's Register  
 Foundation

6.11.45.



In Mr. Ferris to advise  
+ advise Mr. Van  
Dine who will  
call in for the  
letter.

R.D.  
7/11/45



© 2021

Lloyd's Register  
Foundation