

REPORT of SURVEY for REPAIRS & C.

Date of writing Report Jan. 12, 1932 When handed in at Lloyd's Office Jan. 12, 1932 Port of NEW YORK

No. in Reg. Book 26254 Survey held at on the ~~Wood~~ Steel S. S. "LA PLAYA" Date, First Survey --- Last Survey --- 19

TONNAGE - Built at Birkenhead By whom Cammell Laird & Co. Ltd. YEAR 1923 MONTH 11

GROSS 3682 Owners Balboa Shipping Co. Managers United Fruit Co. Owners' Address (if not already recorded in Appendix to Register Book) Port belonging to Balboa

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

WB=CelldBorDBa feet; uE&B feet; f feet tons. FPT tons; APT tons; MT tons. If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 32893 Port N. Yk.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

The Owners have requested that this vessel's classification be withdrawn from this Society (see copy of letter from Owners dated January 7, 1932).

DISCLOSED

SECTION

No. 672

[Handwritten signature]

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Feet) When put on, Month Year
Decks	State if Tanks now tested	Engine Room Skylights	Boats
Caulking of Decks	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Coamings	Ceiling	Scuppers	Condition, how ascertained (State if wedges removed)
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Outside Plating	Rudder	Hatches	Equipment letter
Breasthooks	Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Transoms	Windlass	Caulking ditto	Cables (State if now ranged)
Frames	Have Pumps now been examined and found efficient?	Treenails ditto	" length (on board) size
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	" Rule length size
Longitudinals	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches, ditto	Hawser & Warps
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Floors		Ditto ditto at other places ditto	
Beams		Stringers, Clamps & Shelves ditto	
Stringers		Salting (State if examined.) ditto	
Inner Bottom Plating			

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and pIND24, &c."

Survey Fee (per Section 20)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

[Handwritten signature]
Surveyor to Lloyd's Register of Shipping.
General Committee
Thursday, 28th January 1932

Committee's Minute NEW YORK JAN 18 1932

Character Assigned Withdraw class and insert (...) American Committee's Register decision confirmation

If a survey also been held on the Machinery of the Ship, or when will it be sent?

Is Certificate required? If so, to be sent to