

Class is subject to *the donkey boilers not being used until surveyed.*

19 SEP 1960

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME..... NAVEM HEMBURY..... REPORT..... Rio..... No. 7617.....

ES due 3.60 )  
MBS due 3.60 ) now held and screwshaft examined.  
DBS due 5.58 )

Alterations. The main and donkey boilers now converted to burn oil fuel in accordance with approved plans.

Wear and Tear Repairs. Main crankshaft lifted, bearings remetalled and shafting re-aligned. All preheater tubes renewed in both main boilers.

SRL The donkey boiler now surveyed.

IT IS SUBMITTED that this vessel's machinery is eligible for the records ES 5.60, MBS 5.60, DBS 5.60, TS (CL) 5.60 and SPS 5.60 without special conditions. The machinery is also eligible for the notation 5.60.

*O.F.*



© 2021

*Eul*  
Lloyd's Register  
Foundation  
16.8.60.